

A1.2 Regarding Section 1.3.3

Exemplary arrangement: Cutting plan for all parts (including templates) for a Ls and a Lw

The graphics below show one of several possible layouts for all parts needed on three metal sheets. This means all parts for a LAZOLA Ls (standard) and a LAZOLA Lw (double width) – including the templates. – A rule for this layout was to try to position parts of equal dimensions next to each other, so they can be cut in one go. The parts are arranged so that parts 1 and 2 can be cut first.

