

A3.2

Required tools

Only few tools are required. But care for high quality.



1	stapler
2	Screwdriver for bits
3	Cutter
4	Nipper pliers
5	Steel nail
6	Combination pliers with cutting function
7	Punch
8	Pricker
9	Small saw, e.g hacksaw
10	Medium-weight hammer
11	Plain tinsnips for short cuts
12	Straight cutting tinsnips
13	Small chissel
14	Hand riveter
15	Any block of solid steel as support, e.g. a sledge hammer
16	At least two small Screw clamps. In case that for the wooden frames two 8 mm sheets of plywood have to be glued together, because completely straight 15 mm plywood is not available, 10 more bigger clamps are needed. (see Appendix C-2.4.3)